



Photo 3 – After Remediation Back Yard



Site Photographs –

NON-RESPONSIVE

CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE

Name (please

Daytime Phone

Evening Phone

Email: _____

Address of Property

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Owner

Owner

Owner

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604

59.5
70

22
24


50.5
53.5

CRA
CONESTOGA-ROVERS & ASSOCIATES

PROJECT No.: 39826-19
PROJECT NAME: H. KATMER - OUR
DATE: 5/12/2014

DESIGNED BY: KNEEN
CHECKED BY: _____
PAGE 1 OF 1

NON-RESPONSIVE





Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Parcel Landscape Area

Current Address

Lawn Area

Flowers/Plants:

☐ Yes ☒ No

Soil (grade) next to structure:

☐ Yes ☒ No

Shrubbery:

☐ Yes ☒ No

Trees:

☐ Yes ☒ No

Restoration Plan

Sidewalks

Sidewalk:

☐ Yes ☒ No

Tree Roots:

☐ Yes ☒ No

Sections Missing:

☐ Yes ☒ No

Other: _____

☐ Yes ☒ No

Restoration Plan

Add additional gravel layer to gravel parking area

Signatures

Inspection Form Signatures Before Removal Action

NON-RESPONSIVE

Verbal Approval
12/13/16

Name of Home Owner

Signature

Date

Walter Pochman

GHD

Signature

4/12/17

Date

Inspection Form Signatures After Removal Action

NON-RESPONSIVE

6/1/17

Date

Walter Pochman

GHD

Signature

6/7/17

Date





Photo 1 – Before Remediation Back Yard



Photo 2 – During Remediation Back Yard



Site Photogra

NON-RESPONSIVE



Photo 3 – During Remediation Back Yard (2)



Photo 4 – After Remediation Back Yard



Site Photograph



NON-RESPONSIVE

Name (please print)

Daytime Phone

Evening Phone

Email: _____

Address of Property

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Owner Signature

Owner Name

Owner's Address (if different from the Address listed above): _____

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604


CRA

CONESTOGA-ROVERS & ASSOCIATES

NON-RESPONSIVE

PROJECT No.: 39826-19
PROJECT NAME: _____
DATE: 4/11/10

DESIGNED BY: _____
CHECKED BY: _____
PAGE _____ OF _____





Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Parcel Landscape Area

Current Address

Lawn Area

Flowers/Plants:

☒ Yes ☐ No

Soil (grade) next to structure:

☐ Yes ☐ No

Shrubbery:

☒ Yes ☐ No

Trees:

☒ Yes ☐ No

Restoration Plan

Tomatoe Plants

Rose Bushes (2 stay (east) & 2 go (west))

Save maple, peach, pine, flower & small next to garage

Sidewalks

Sidewalk:

☐ Yes ☐ No

Tree Roots:

☒ Yes ☐ No

Sections Missing:

☐ Yes ☐ No

Other: _____

☒ Yes ☐ No

Restoration Plan

Replace river rock

\$200 for ripped flowers & vegetation

EDIT (11/17/17): ONLY TOOK OUT TOMATOE PLANTS. GIVING \$80 FOR VEGGIES.

Signatures Non-Responsive
Non-Responsive

NON-RESPONSIVE

Ivan Navarro
GHD

[Signature]
Signature

9/26/17
Date

NON-RESPONSIVE

Ivan Navarro
GHD

[Signature]
Signature

11/12/17
Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

Current Address:

Description

• Elevated garden up front is built with landscape block. 2.5ft above grade set on concrete.

Sketch of Property






Photo 1 – Before Remediation Under Deck



Photo 2 – Before Remediation Back West Garden



Site Photographs

NON-RESPONSIVE



Photo 3 – Before Remediation Back South Gardens




Photo 4 – Before Remediation Back East Garden



Site Photographs

NON-RESPONSIVE



Photo 5 – During Remediation Back East Garden



Photo 6 – During Remediation Back South Garden



Site Photographs –

NON-RESPONSIVE



Photo 7 – During Remediation Back West Garden



Photo 8 – During Remediation Under Deck



Site Photographs –






Photo 9 – After Remediation Back East Garden



Photo 6 – After Remediation Back South Garden



Site Photographs

NON-RESPONSIVE



Photo 6 – After Remediation Back West Garden



Site Photographs –

NON-RESPONSIVE

CONSENTIMIENTO PARA EL ACCESO A LA PROPIEDAD

NON-RESPONSIVE

Nombre (en letra de molde)

Teléfono durante el día:

Teléfono después de horas:

Email: _____

Dirección completa de _____

Doy mi consentimiento a los funcionarios, empleados, contratistas y representantes autorizados de la Agencia de Protección Ambiental de los Estados Unidos (EPA) y / o de H. Kramer & Company (H. Kramer) para que entren y tengan acceso continuo a la propiedad indicada arriba para realizar las siguientes acciones de respuesta:

- (1) Recolección de muestras de la superficie y bajo la superficie incluyendo – pero sin limitarse – a la tierra y al aire;
- (2) Documentación de las observaciones científicas y de ingeniería incluyendo – pero sin limitarse – a tomar notas, fotografías y estudios topográficos;
- (3) Eliminación de tierra contaminada y actividades relacionadas;
- (4) Cumplimiento con las medidas de restauración una vez que se haya removido la tierra contaminada incluyendo el suministro de tierra impoluta por la tierra removida, el suministro de césped para las áreas previamente cubiertas de hierba, la restauración limitada del jardín, la sustitución de grava, el reparo de posibles daños o por pérdida de propiedad como resultado directo del muestreo, la remoción, y las actividades de restauración; y
- (5) Otras acciones que sean necesarias para proteger la salud humana y el medio ambiente según determine el coordinador de acciones en terreno de la EPA.

Entiendo que estas posibles acciones se llevan a cabo de acuerdo con las autoridades de respuesta según la Ley de Responsabilidad, Compensación y Recuperación Ambiental de 1980, según enmendada, 42 USC Sección 9601 *et seq.*

Yo doy este permiso escrito voluntariamente, en nombre mío y de todos los otros dueños de la propiedad, con el conocimiento de mi derecho a revocar mi consentimiento voluntario en cualquier momento, y sin ningún tipo de amenaza o promesa. Entiendo que la EPA, H. Kramer, o sus representantes autorizados se pondrán en contacto conmigo antes del inicio de cualquier investigación o actividad de restauración en mi propiedad, y voy a notificar a todo inquilino en mi propiedad de cualquier investigación o actividad de restauración.

Este documento debe ser firmado únicamente por el propietario legal de la propiedad indicada arriba

NON-RESPONSIVE

Por favor, firme y devuelva este formulario a:
Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



Property Inspection Form – Pilsen OU2 Area

Structure


NON-RESPONSIVE

Current Address:

Description

Rose bush on backyard.. Garage on grade onto alley. Garden & Back Yard
4 feet below grade. Manhole on front yard.

Sketch of Property





Property Inspection Form – Pilsen OU2 Area

Parcel Landscape Area

Current Address

NON-RESPONSIVE

Lawn Area

Flowers/Plants:

☒ Yes ☐ No

Soil (grade) next to structure:

☒ Yes ☐ No

Shrubby:

☐ Yes ☐ No

Trees:

☐ Yes ☐ No

Restoration Plan

Tenant will remove plants/flowers

Yard will get 8" of gravel - they will be placing caliche

Sidewalks

Sidewalk:

☐ Yes ☐ No

Tree Roots:

☐ Yes ☐ No

Sections Missing:

☐ Yes ☐ No

Other: _____

☒ Yes ☐ No

Restoration Plan

Front yard will get gravel (onto grade)
- Garden will get sod mulch.

Signatures

Property owner gave the OK for tenant to sign form

Inspection Form Signatures Before Removal Action

NON-RESPONSIVE

07/24/17
Date

GHD
Juan Navarro

Signature
Juan D. Lavane

07/24/17
Date

NON-RESPONSIVE

08/08/17
Date

GHD
Juan Navarro

Signature
[Signature]

08/08/17
Date



Property Inspection Form – Pilsen OU2 Area


NON-RESPONSIVE

Structure

nt Address:

Description

Sketch of Property






Photo 1 – Before Remediation Backyard & Garden



Photo 2 – Before Remediation Front Yard



Site Photogra

NON-RESPONSIVE



Photo 3 – During Remediation Front Yard



Photo 4 – During Remediation Backyard & Garden



Site Photogra

NON-RESPONSIVE



Photo 5 – During Remediation Backyard & Garden (2)



Photo 6 – After Remediation Backyard & Garden



Site Photogra

NON-RESPONSIVE



Photo 7 – After Remediation Front Yard



Site Photograph

NON-RESPONSIVE

NON-RESPONSIVE

CONSENT FOR ACCESS TO PROPERTY

Name

Day

Even

Email

Address

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



Property Inspection Form – Pilsen OU2 Area


Structure

NON-RESPONSIVE

Current Address:

Description

Sketch of Property





Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Parcel Landscape Area

Current Address

Lawn Area

Restoration Plan

Flowers/Plants:

☐ Yes ☒ No

Soil (grade) next to structure:

☒ Yes ☐ No

Shrubbery:

☐ Yes ☒ No

Trees:

☒ Yes ☐ No

NEXT TO BUILDING & DECK COLUMNS

LARGE STUMP ON NORTH SIDE OF BACKYARD

Sidewalks

Restoration Plan

Sidewalk:

☐ Yes ☐ No

Tree Roots:

☒ Yes ☐ No

Sections Missing:

☐ Yes ☐ No

Other: _____

☐ Yes ☐ No

SEE PROPERTY SKETCH FOR DETAILS

GRAVEL UNDER DECK, AROUND THE PAVERS,
& UNDER PAVERS

NON-RESPONSIVE

Signatures

Inspection Firm
NON-RESPONSIVE

7/3/18

Ivan Navarro
GHD

[Signature]
Signature

07/03/18
Date

NON-RESPONSIVE

Inspection Firm Signatures After Removal Action

Ivan Navarro
GHD

[Signature]
Signature

07/06/18
Date

07/06/18
Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

Current Address:

Description

Sketch of Property






Photo 1 – Before Remediation Backyard



Photo 2 – Before Remediation Sideyard



Site Photographs –

NON-RESPONSIVE



Photo 3 – Before Remediation Sideyard (2)



Photo 4 – During Remediation Backyard



Site Photographs –

NON-RESPONSIVE



Photo 5 –During Remediation Sideyard



Photo 6 – After Remediation Backyard & Sideyard



Site Photographs

NON-RESPONSIVE



Photo 7 – After Remediation Front Yard & Front Garden 2



Photo 8 – After Remediation Sideyard



Site Photographs –

NON-RESPONSIVE

CONSENTIMIENTO PARA EL MUESTREO

NON-RESPONSIVE

Nombre (en letra de m

Teléfono durante el día

Teléfono después de h

Email: _____

Dirección completa de

Doy mi consentimiento a los funcionarios, empleados, contratistas y representantes autorizados de la Agencia de Protección Ambiental de los Estados Unidos (EPA) y / o de H. Kramer & Company (H. Kramer) para que entren y tengan acceso continuo a la propiedad indicada arriba para realizar las siguientes acciones de respuesta:

- (1) Recolección de muestras de la superficie y bajo la superficie incluyendo – pero sin limitarse – a la tierra y al aire;
- (2) Documentación de las observaciones científicas y de ingeniería incluyendo – pero sin limitarse – a tomar notas, fotografías y estudios topográficos;
- (3) Eliminación de tierra contaminada y actividades relacionadas;
- (4) Cumplimiento con las medidas de restauración una vez que se haya removido la tierra contaminada incluyendo el suministro de tierra impoluta por la tierra removida, el suministro de césped para las áreas previamente cubiertas de hierba, la restauración limitada del jardín, la sustitución de grava, el reparo de posibles daños o por pérdida de propiedad como resultado directo del muestreo, la remoción, y las actividades de restauración; y
- (5) Otras acciones que sean necesarias para proteger la salud humana y el medio ambiente según determine el coordinador de acciones en terreno de la EPA.

Entiendo que estas posibles acciones se llevan a cabo de acuerdo con las autoridades de respuesta según la Ley de Responsabilidad, Compensación y Recuperación Ambiental de 1980, según enmendada, 42 USC Sección 9601 *et seq.*

Yo doy este permiso escrito voluntariamente, en nombre mío y de todos los otros dueños de la propiedad, con el conocimiento de mi derecho a revocar mi consentimiento voluntario en cualquier momento, y sin ningún tipo de amenaza o promesa. Entiendo que la EPA, H. Kramer, o sus representantes autorizados se pondrán en contacto conmigo antes del inicio de cualquier investigación o actividad de restauración en mi propiedad, y voy a notificar a todo inquilino en mi propiedad de cualquier investigación o actividad de restauración.

Este documento debe ser firmado únicamente por el propietario legal de la propiedad indicada arriba.

NON-RESPONSIVE

Firma del propietario: _____

Nombre del propietario: _____

Dirección completa del dueño (si es diferente a la dirección que aparece arriba): _____

Por favor, firme y devuelva este formulario a:
Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



Property Inspection Form – Pilsen OU2 Area


NON-RESPONSIVE

Structure

Current Address:

Description

Sketch of Property





Property Inspection Form – Pilsen OU2 Area

Parcel Landscape Area

Current Address

NON-RESPONSIVE

Lawn Area

Flowers/Plants:

☒ Yes ☐ No

Soil (grade) next to structure:

☒ Yes ☒ No

Shrubby:

☐ Yes ☒ No

Trees:

☐ Yes ☒ No

Restoration Plan

ONE ROSE BUSH - \$40 TO REPLACE

Sidewalks

Sidewalk:

☒ Yes ☐ No

Tree Roots:

☐ Yes ☒ No

Sections Missing:

☐ Yes ☒ No

Other: _____

☒ Yes ☐ No

Restoration Plan

SEE PROPERTY SKETCH FOR DETAILS

56' x 1' WILL BE GRAVEL, 20' x 1' WILL BE SO

Signatures

NON-RESPONSIVE

Ivan Navarro
GHD

Signature

06/08/2018
Date

NON-RESPONSIVE

Ivan Navarro
GHD

Signature

06/08/18
Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

Current Address:

Description

Sketch of Property






Photo 1 – Before Remediation Side Strip



Photo 2 – Before Remediation Side Strip (2)



Site Photogra

NON-RESPONSIVE



Photo 3 – During Remediation Side Strip



Photo 4 – During Remediation Side Strip (2)



Site Photograph

NON-RESPONSIVE



Photo 5 – After Remediation Side Strip



Photo 6 – After Remediation Side Strip (2)



Site Photograph

NON-RESPONSIVE

CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE

Name (please print)

Daytime Phone Number

Evening Phone Number

Email: _____

Address of Property

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Owner Signature:

Owner Name (print)

Owner's Address (if different from the Address listed above): _____

Please sign and return this form to:
Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604

CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE


Current Address:

Structure

Description

XRF SCAN DONE BY TETRA TECH - SEE LOGBOOK FOR READINGS

Sketch of Property





Property Inspection Form – Pilsen OU2 Area

Parcel Landscape Area

Current Add

NON-RESPONSIVE

Lawn Area

Flowers/Plants:

☐ Yes ☒ No

Soil (grade) next to structure:

☒ Yes ☐ No

Shrubbery:

☐ Yes ☒ No

Trees:

☐ Yes ☒ No

Restoration Plan

SIDEWALK, DRIVEWAY & PATHS

Sidewalks

Sidewalk:

☒ Yes ☐ No

Tree Roots:

☒ Yes ☐ No

Sections Missing:

☐ Yes ☐ No

Other: _____

☒ Yes ☐ No

Restoration Plan

FROM NEIGHBOR TREE

SEE PROPERTY SKETCH FOR DETAILS

Signatures

NON-RESPONSIVE

07/06/18

Ivan Navarro

GHD

Ivan Navarro

Signature

07/06/18

Date

NON-RESPONSIVE

7/11/18

Ivan Navarro

GHD

Ivan Navarro

Signature

7/11/18

Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

rent Address:

Description

Sketch of Property






Photo 1 – Before Remediation Backyard



Photo 2 – During Remediation Backyard



Site Photographs

NON-RESPONSIVE



Photo 3 – During Remediation Backyard (2)



Photo 4 – Owner Concrete Pour



Site Photographs

NON-RESPONSIVE



Photo 5 – Owner Concrete Pour (2)



Photo 6 – After Remediation Backyard & Garden



Site Photographs –

NON-RESPONSIVE

CONSENTIMIENTO PARA EL ACCESO A LA PROPIEDAD

NON-RESPONSIVE

Nombre

Teléfono

Teléfono

Correo electrónico

Dirección

Doy mi consentimiento a los funcionarios, empleados, contratistas y representantes autorizados de la Agencia de Protección Ambiental de los Estados Unidos (EPA) y / o de H. Kramer & Company (H. Kramer) para que entren y tengan acceso continuo a la propiedad indicada arriba para realizar las siguientes acciones de respuesta:

- (1) Recolección de muestras de la superficie y bajo la superficie incluyendo – pero sin limitarse – a la tierra y al aire;
- (2) Documentación de las observaciones científicas y de ingeniería incluyendo – pero sin limitarse – a tomar notas, fotografías y estudios topográficos;
- (3) Eliminación de tierra contaminada y actividades relacionadas;
- (4) Cumplimiento con las medidas de restauración una vez que se haya removido la tierra contaminada incluyendo el suministro de tierra impoluta por la tierra removida, el suministro de césped para las áreas previamente cubiertas de hierba, la restauración limitada del jardín, la sustitución de grava, el reparo de posibles daños o por pérdida de propiedad como resultado directo del muestreo, la remoción, y las actividades de restauración; y
- (5) Otras acciones que sean necesarias para proteger la salud humana y el medio ambiente según determine el coordinador de acciones en terreno de la EPA.

Entiendo que estas posibles acciones se llevan a cabo de acuerdo con las autoridades de respuesta según la Ley de Responsabilidad, Compensación y Recuperación Ambiental de 1980, según enmendada, 42 USC Sección 9601 *et seq.*

Yo doy este permiso escrito voluntariamente, en nombre mío y de todos los otros dueños de la propiedad, con el conocimiento de mi derecho a revocar mi consentimiento voluntario en cualquier momento, y sin ningún tipo de amenaza o promesa. Entiendo que la EPA, H. Kramer, o sus representantes autorizados se pondrán en contacto conmigo antes del inicio de cualquier investigación o actividad de restauración en mi propiedad, y voy a notificar a todo inquilino en mi propiedad de cualquier investigación o actividad de restauración.

Este documento debe ser firmado únicamente por el propietario legal de la propiedad indicada arriba.

NON-RESPONSIVE

Firma del propietario

Nombre del propietario

Dirección completa del dueño (si es diferente a la dirección que aparece arriba): _____

CONESTOGA-ROVERS & ASSOCIATES

NON-RESPONSIVE


PROJECT NAME: _____

DATE: 9/11/16

DESIGNED BY: _____

CHECKED BY: _____

PAGE _____ OF _____





Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Parcel Landscape Area

Current Address

Lawn Area

Flowers/Plants:

☒ Yes ☐ No

Soil (grade) next to structure:

☒ Yes ☐ No

Shrubbery:

☐ Yes ☒ No

Trees:

☒ Yes ☐ No

Restoration Plan

Keeping Rose tree up front & Small pine
- Owner wants gravel on side garden &
front garden.
- Keep some small trees from east side &

- Save bricks ^{away} ~~from~~ ~~gravel~~ ~~stone~~
- take down all trees from west side

Sidewalks

Sidewalk:

☐ Yes ☒ No

Tree Roots:

☒ Yes ☐ No

Sections Missing:

☐ Yes ☒ No

Other: _____

☒ Yes ☐ No

Restoration Plan

plant
- Keep small shrub on west garden

Signatures

EDIT. (05/08/17): Wants gravel all around (side ^{both} gardens), Does not want the trees anymore.

Inspection Form Signatures Before Removal Action

NON-RESPONSIVE

5-5-2017

Date

Ivan Navarro
GHD

Signature

05/05/17
Date

NON-RESPONSIVE

5-9-17

Date

Ivan Navarro
GHD

Signature

05/09/17
Date



Property Inspection Form – Pilsen OU2 Area

Parcel Landscape Area

Current Address **NON-RESPONSIVE**

Lawn Area

Flowers/Plants: ☐ Yes ☒ No
Soil (grade) next to structure: ☐ Yes ☒ No
Shrubby: ☐ Yes ☒ No
Trees: ☐ Yes ☒ No

Restoration Plan

Sidewalks

Sidewalk: ☒ Yes ☐ No
Tree Roots: ☐ Yes ☒ No
Sections Missing: ☒ Yes ☐ No
Other: ☐ Yes ☐ No

Restoration Plan

East from gravel placement.
3 inches of gravel will be placed on dirt section

Signatures

Inspection Form Signatures Before Removal Action

NON-RESPONSIVE

8-9-17
Date

Ivan Navano
GHD

Ivan Navano
Signature

08/09/17
Date

NON-RESPONSIVE

8-9-17
Date

Ivan Navano
GHD

Ivan Navano
Signature

08/09/17
Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

Current Address:

Description

EXCAVATED AROUND ROSE VINE & WITHOUT EXPOSING ROOTS TO MUCH. PLACED
CLEAN SOIL ON VINE. SAME WAS DONE WITH SMALL PINE.

- AUGUST REVISIT = GRAVEL PART WAS SCANNED WITH XRF - ABOVE THRESHOLD

REMOVING TOP GRAVEL LAYER & PLACING CLEAN GRAVEL. BRICK LAYER
UNDER GRAVEL. OBTAINED SECOND SIGNATURE

Sketch of Property






Photo 1 – Before Remediation West Strip



Photo 2 – Before Remediation Front Gardens



Site Photograph

NON-RESPONSIVE



Photo 3 – Before Remediation East Strip



Photo 4 – Before Remediation Backyard



Site Photogra

NON-RESPONSIVE



Photo 5 – During Remediation West Strip



Photo 6 – During Remediation East Strip



Site Photograph

NON-RESPONSIVE



Photo 7 – During Remediation Backyard



Photo 8 – After Remediation Backyard



Site Photograph

NON-RESPONSIVE



Photo 9 – After Remediation West Strip



Photo 10 – After Remediation Front Gardens



Site Photograph





Photo 11 – After Remediation East Strip



Site Photogra

NON-RESPONSIVE

CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE

Name _____

Daytime _____

Evening _____

Email _____

Address _____

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Please sign and return this form to:
Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604

CRA

1343

CONESTOGA-ROVERS & ASSOCIATES

NON-RESPONSIVE

PROJECT No.: 39826-19

PROJECT NAME:

DATE: 4/12/16

DESIGNED BY:

CHECKED BY:

PAGE OF






Photo 1 – Back Yard

Site Photographs –

NON-RESPONSIVE



CONSENT FOR ACCESS TO PROPERTY

NON-RESPONSIVE

Name

Date

Event

Emergency

Address

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property.

NON-RESPONSIVE

Owner

Owner

Owner

Owner

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604

CRA

CONESTOGA-ROVERS & ASSOCIATES

NON-RESPONSIVE

PROJECT No.: 39826-19

PROJECT NAME: _____

DATE: 4/7/16

DESIGNED BY: _____


CHECKED BY: _____

PAGE _____ OF _____

Back garden
S-160407-gw-028
@ 10:20

24.
Garden
S-160407-gw-027
@ 10:00
2-point

Alley



Note:
Soil samples were full
soil w/ bricks and gravel
removed bricks and gravel

Particulate
readings well
below action
levels

W. 19th Street

Black w/
Chain link
fence



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Parcel Landscape Area

Current Ac

Lawn Area

Restoration Plan

Flowers/Plants:

☐ Yes ☐ No

Soil (grade) next to structure:

☐ Yes ☐ No

Shrubbery:

☒ Yes ☐ No

Trees:

☐ Yes ☐ No

BUSH ON NORTH SIDE WILL BE SAVED

Sidewalks

Restoration Plan

Sidewalk:

☐ Yes ☐ No

Tree Roots:

☒ Yes ☐ No

Sections Missing:

☐ Yes ☐ No

Other: _____

☐ Yes ☐ No

BUSH ON NORTH SIDE

YARD WILL GET SOIL & GRASS SEEDS WILL GET
DIRT

Signatures

Non-Responsive
Non-Responsive

Non-Responsive Form Signatures Before Removal Action

NON-RESPONSIVE

4/17/2018
Date

Ivan Navarro

GHD

Ivan Navarro
Signature

4/17/2018
Date

NON-RESPONSIVE

4/27/2018
Date

Ivan Navarro

GHD

Ivan Navarro
Signature

4/27/2018
Date



Property Inspection Form – Pilsen OU2 Area

Structure

NON-RESPONSIVE

Current Address:

Description

- BRING SOD ON YARD UP TO SIDEWALK. SLOPE DOWN TO ALLEY GRAPIC

Sketch of Property






Photo 1 – Before Remediation Under Stairs



Photo 2 – Before Remediation Back Garden



Site Photograph

NON-RESPONSIVE



Photo 3 – Before Remediation Backyard



Photo 4 – During Remediation Backyard



Site Photographs

NON-RESPONSIVE



Photo 5 – During Remediation Back Garden



Photo 6 – After Remediation Under Stairs



Site Photographs –

NON-RESPONSIVE



Photo 7 – After Remediation Back Garden



Photo 8 – After Remediation Backyard



Site Photographs –

NON-RESPONSIVE

NON-RESPONSIVE

CONSENT FOR ACCESS TO PROPERTY

Name (please print)

Daytime Phone

Evening Phone

Email: _____

Address of Property

I consent to officers, employees, contractors, and authorized representatives of the United States Environmental Protection Agency (EPA) and/or of H. Kramer & Company (H. Kramer) entering and having continued access to the property described above to perform the following response actions:

- (1) Collecting samples, surface and subsurface, including but not limited to soil and air;
- (2) The documenting of scientific and engineering observations, including, but not limited to taking notes, photographs, and surveying;
- (3) Removing contaminated soil and related activities;
- (4) Completing restoration efforts once contaminated soil has been removed to include replacement of removed soil with clean soil, re-sodding of previously grass covered areas, limited landscaping restoration, replacement of gravel, repair of possible damage or property loss as a direct result of sampling, removal, and restoration activities; and
- (5) Other such actions as the EPA On-Scene Coordinator determines may be necessary to protect human health and the environment.

I realize that these possible actions are being undertaken pursuant to the response authorities under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, 42 U.S.C. Section 9601 *et seq.*

I give this written permission voluntarily, on behalf of myself and all other co-owners of the Property, with knowledge of my right to revoke my voluntary consent at any time, and without threats or promises of any kind. I understand that EPA, H. Kramer, or their authorized representatives will contact me before the start of any investigation or remedial activities on my property, and I will notify any tenants in my property of any such investigation or remedial activities.

This document should be signed only by the legal owner of the property described above.

NON-RESPONSIVE

Please sign and return this form to:

Heriberto León, EPA Region 5 (SI-7J), 77 West Jackson Blvd., Chicago, IL 60604



Property Inspection Form – Pilsen OU2 Area


NON-RESPONSIVE

Structure

Current Address:

Description

Sketch of Property





Property Inspection Form – Pilsen OU2 Area

Parcel Landscape Area

Current Address: NON-RESPONSIVE

Lawn Area

Flowers/Plants: ☐ Yes ☒ No
Soil (grade) next to structure: ☐ Yes ☒ No
Shrubby: ☐ Yes ☒ No
Trees: ☐ Yes ☒ No

Restoration Plan

Sidewalks

Sidewalk: ☒ Yes ☐ No
Tree Roots: ☐ Yes ☒ No
Sections Missing: ☐ Yes ☒ No
Other: ☒ Yes ☐ No

Restoration Plan

Front yard - excavated 1ft and replaced with soil & sod.

Signatures

Inspection Form Signatures Before Removal Action

NON-RESPONSIVE

7-10-17

Date

Ivan Navarrete

GHD

Ivan Navarrete

Signature

07/10/17

Date

NON-RESPONSIVE

NON-RESPONSIVE

7-13-17

Date

Ivan Navarrete

GHD

Ivan Navarrete

Signature

7/13/17

Date



Property Inspection Form – Pilsen OU2 Area

NON-RESPONSIVE

Structure

Current Address:

Description

Sketch of Property






Photo 1 – Before Remediation Front Yard



Photo 2 – Before Remediation Front Yard (2)



Site Photograph

NON-RESPONSIVE